



2/22



<u>-1</u>6.2





<u>G</u>.4





FIG. 5



TOBURO. WARDIGOD

FIG. 6





FIG. 7









FIG. 9


9/22

integrated heat quantity control flow chart



ogores 243 

FIG. 10




A: polishing cloth surface temperature

B: polishing agent solution return temperature (S<sub>6</sub>) C: polishing agent solution supply temperature (S<sub>1</sub>)


polishing agent solution supply rate 30 l/min

FIG. 11



Dogracus ograci

FIG. 12




A: polishing cloth surface temperature

B: polishing agent solution supply temperature

 $\boldsymbol{\mathsf{C}}\,:\,\mathsf{polishing}$  agent solution return temperature

D : polishing table cooling water supply temperature E : polishing table cooling water return temperature

FIG. 13



TOSSEO ENSESED




FIG. 15

integrated heat quantity control flow chart





FIG. 16






FIG. 17




FIG. 18






FIG. 19



19/22








FIG. 22








FIG. 23

